

MAINTENANCE HISTORY

Generation date: 2025/11/27

Plate Number	K0-30-BP
Make	PEUGEOT
Model	108
Vehicle Description	Allure 1.0 e-VTi 72pk 5d

[illegible]

				- LeasePlan Nederland N.V., , - Vakgarage 't Centrum, ,
2023/07/21	35898 KM	repair	- Peugeot OHbeurt - NVT - Uitvoeren Derde remlicht - - Electrische storing - Vervangen Int luchtfilter - versleten - Vervangen Remvloeistof - versleten - Vervangen Riem/multiriem - versleten - Vervangen	- Bosch Car Service Park Honingen, , - Bosch Car Service Park Honingen, , - Bosch Car Service Park Honingen, , - Bosch Car Service Park Honingen, , - Bosch Car Service Park Honingen, , - Bosch Car Service Park Honingen, ,
2022/08/02	18565 KM	repair	- Peugeot OHbeurt - NVT - Uitvoeren Diverse lampjes - Werkt niet - Vervangen Ruitenw.blad V - versleten - Vervangen	- Profile Schiedam, Nooteboom, , - Profile Schiedam, Nooteboom, , - Profile Schiedam, Nooteboom, ,