



PEUGEOT EXPERT (31)
EXPERT FGN TOLE STANDARD BLUEHDI
145 S&S EAT8 PREMIUM

VIN NO VF3VFEHS7MZ116540
Registration Number GD752VZ



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250725113622
Inspection Date / Place	2025-07-25 / BCA NANTES	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	White	Engine Size (cc)	1997
Engine Size	2.0	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Rear parking sensors	Power assisted steering	Radio
Cruise control			

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres


Left Front Tyre Depth	7	Left Rear Tyre Depth	7
Right Rear Tyre Depth	7	Right Front Tyre Depth	7

Cosmetic Damage

35 Dommages



0 Dommages




Component		Damage	Comments
1	Side Panel / Back Left	Bodywork / Dent / Dent	
2	Side Panel / Back Left	Bodywork / Dent / Dent	
3	Door / Front Left	Paint / Chipping	
4	Door Side Molding / Front Left	Paint / Scratch / Line	
5	Mirror / Front Left	Paint / Scratch / Line	
6	Bumper / Front	Paint / Scratch / Line	
7	Bumper / Front	Paint / Scratch / Line	
8	Bumper / Front	Paint / Scratch / Line	
9	Hood	Paint / Chipping	
10	Fender / Front Right	Bodywork / Dent / Dent	
11	Fender / Front Right	Bodywork / Dent / Dent	
12	Fender / Front Right	Paint / Scratch / Line	
13	Mirror / Front Right	Paint / Scratch / Line	


14	Door / Front Right	Bodywork / Dent / Dent
15	Door / Front Right	Paint / Scratch / Line
16	Door Side Molding / Front Right	Paint / Scratch / Line
17	Rocker Panel / Center Right	Bodywork / Dent / Dent
18	Side Panel / Back Right	Bodywork / Dent / Dent
19	Side Panel / Back Right	Bodywork / Dent / Dent
20	Side Panel / Back Right	Bodywork / Dent / Dent
21	Side Panel / Back Right	Bodywork / Dent / Dent
22	Side Panel / Back Right	Bodywork / Dent / Dent
23	Door / Back Right	Bodywork / Dent / Dent
24	Door Side Molding / Back Right	Paint / Scratch / Line
25	Door / Back Right	Bodywork / Dent / Dent
26	Door / Back Right	Bodywork / Dent / Dent
27	Shield / Back	Paint / Scratch / Line
28	Shield / Back	Bodywork / Dent / Dent
29	Shield / Back	Paint / Scratch / Line
30	Shield / Back	Paint / Scratch / Line
31	Tailgate	Bodywork / Dent / Dent
32	Tailgate	Bodywork / Dent / Dent
33	Tailgate	Bodywork / Dent / Dent
34	Tailgate	Bodywork / Dent / Dent
35	Tailgate	Bodywork / Dent / Dent




1. Side Panel / Back Left
Bodywork / Dent / Dent -



2. Side Panel / Back Left
Bodywork / Dent / Dent -



3. Door / Front Left
Paint / Chipping -



4. Door Side Molding / Front Left
Paint / Scratch / Line -



5. Mirror / Front Left
Paint / Scratch / Line -



6. Bumper / Front
Paint / Scratch / Line -



7. Bumper / Front
Paint / Scratch / Line -




8. Bumper / Front
Paint / Scratch / Line -



9. Hood
Paint / Chipping -



10. Fender / Front Right
Bodywork / Dent / Dent -



11. Fender / Front Right
Bodywork / Dent / Dent -




12. Fender / Front Right
Paint / Scratch / Line -



13. Mirror / Front Right
Paint / Scratch / Line -



14. Door / Front Right
Bodywork / Dent / Dent -




15. Door / Front Right
Paint / Scratch / Line -



16. Door Side Molding / Front Right
Paint / Scratch / Line -




17. Rocker Panel / Center Right
Bodywork / Dent / Dent -



18. Side Panel / Back Right
Bodywork / Dent / Dent -



19. Side Panel / Back Right
Bodywork / Dent / Dent -




20. Side Panel / Back Right
Bodywork / Dent / Dent -



21. Side Panel / Back Right
Bodywork / Dent / Dent -



22. Side Panel / Back Right
Bodywork / Dent / Dent -



23. Door / Back Right
Bodywork / Dent / Dent -



24. Door Side Molding / Back Right
Paint / Scratch / Line -



25. Door / Back Right
Bodywork / Dent / Dent -



26. Door / Back Right
Bodywork / Dent / Dent -



27. Shield / Back
Paint / Scratch / Line -



28. Shield / Back
Bodywork / Dent / Dent -



29. Shield / Back
Paint / Scratch / Line -



30. Shield / Back
Paint / Scratch / Line -



31. Tailgate
Bodywork / Dent / Dent -



32. Tailgate
Bodywork / Dent / Dent -



33. Tailgate
Bodywork / Dent / Dent -



34. Tailgate
Bodywork / Dent / Dent -



35. Tailgate
Bodywork / Dent / Dent -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

Equipments Test

Convertible, Sunroof, Wagon,
Flatbed truck, Tailgate
electrics test

NA

Dump / Trail / Tail Gate Lift

NA

Main & Spare Keys
Functioning



Central Locking



Electric Windows



Audio Equipment



Navigation System

NA

AC / Heating System



Parking Sensors / Cameras
Functioning



Comments

Comments

Mauvais changement de
rapport (molette bug)

Engine

Serpentine Belt

NA

Cross Member

NA

Control Liquid Leak

NA

Levels

Coolant Fluid - Condition

NA

Oil - Condition



Level - Oil



Brakes Fluid



Coolant Fluid



Dashboard Lights

Dashboard Working



Engine Light



Oil Pressure Warning Light



Airbag Warning Light



Brake Warning Light



Level - Fuel / Battery

5

ABS Warning Light



Transmission Warning Light



Diesel Particulate Filter Light



ESP Fault/Traction Control
Malfunction Light



4WD Light

NA

Service Light



Steering Fluid Level

NA

Hybrid/EV			
Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		

Test Drive Inspection

Test Drive			
Vehicle Starts	✓	Engine functioning	✓
Engine / Aux Belt / Pulley Noise	✓	Steering Noise/Gripping	✓
Smoke Quantity	✓	Transmission	!
Engine Power	✓	Steering	✓
Clutch Functioning	!	Brakes Functionning	✓

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ⊠ Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.