



PEUGEOT 207 Diesel

207 1.6 hdi 16v XS 5p FL

VIN NO VF3WC9HXC9W073804
Registration Number DX874DL



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-07-04	-	-	187990 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2009-07-30	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251009154555
Inspection Date / Place	2025-10-09 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	117

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Parcel Shef	Remote central locking
Tyre Mobility Kit	Power assisted steering	Digital Radio	Remote adjusting wing mirrors
Trip Computer	Stability control		


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	MICHELIN	195/55//R16 - 91V / 2 mm
	MICHELIN	195/55//R16 - 91V / 2 mm
	MICHELIN	195/55//R16 - 91V / 2 mm
	MICHELIN	195/55//R16 - 91V / 2 mm

Cosmetic Damage

21 Danni



5 Danni



Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Panel Filling / Front Right	Interior / Broken	
3	Steering Wheel / Front	Interior / Worn - out	
4	Shield Grid / Front Center	Paint / Scratch / Line	
5	Mirror Shell / Front Right	Bodywork / Poor Previous Repair	
6	Panel Filling / Back Right	Interior / Broken	
7	Bumper / Back	Bodywork / Breakage	
8	Panel Filling / Back Left	Interior / Broken	
9	Panel Filling / Front Left	Interior / Broken	
10	Mirror Shell / Front Left	Paint / Scratch / Line	
11	Rim / Front Left	Out of Bodywork / Scratch	
12	Rocker Panel / Center Right	Bodywork / Dent	

13	Rim / Front Right	Out of Bodywork / Scratch
14	Rim / Back Right	Out of Bodywork / Scratch
15	Trunk Tailgate Handle / Back	Bodywork / Breakage
16	Door / Front Left	Bodywork / Dent
17	Fender / Back Left	Bodywork / Dent
18	Door / Back Right	Bodywork / Dent
19	Bumper / Front	Bodywork / Dent
20	Rim / Back Left	Out of Bodywork / Scratch
21	Fender / Back Right	Paint / Scratch / Line
22	Door / Front Left	Paint / Scratch / Line
23	Mirror Shell / Front Right	Paint / Scratch / Line
24	Tailgate	Bodywork / Dent
25	Door / Back Left	Paint / Chipping
26	Rocker Panel / Center Left	Bodywork / Dent



1. Windshield / Front
Glass Break / Impact -



2. Panel Filling / Front Right
Interior / Broken -



3. Steering Wheel / Front
Interior / Worn - out -



4. Shield Grid / Front Center
Paint / Scratch / Line -



5. Mirror Shell / Front Right
Bodywork / Poor Previous Repair -



6. Panel Filling / Back Right
Interior / Broken -



7. Bumper / Back
Bodywork / Breakage -



8. Panel Filling / Back Left
Interior / Broken -



9. Panel Filling / Front Left
Interior / Broken -



10. Mirror Shell / Front Left
Paint / Scratch / Line -



11. Rim / Front Left
Out of Bodywork / Scratch -



12. Rocker Panel / Center Right
Bodywork / Dent -



13. Rim / Front Right
Out of Bodywork / Scratch -



14. Rim / Back Right
Out of Bodywork / Scratch -



15. Trunk Tailgate Handle / Back
Bodywork / Breakage -



16. Door / Front Left
Bodywork / Dent -



17. Fender / Back Left
Bodywork / Dent -




18. Door / Back Right
Bodywork / Dent -



19. Bumper / Front
Bodywork / Dent -



20. Rim / Back Left
Out of Bodywork / Scratch -



21. Fender / Back Right
Paint / Scratch / Line -



22. Door / Front Left
Paint / Scratch / Line -



23. Mirror Shell / Front Right
Paint / Scratch / Line -



24. Tailgate
Bodywork / Dent -



25. Door / Back Left
Paint / Chipping -



26. Rocker Panel / Center Left
Bodywork / Dent -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	⚠		
Clutch			
Clutch Functioning	⚠		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	⚠		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	⚠
Engine Noise	⚠		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

⚠ Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested