



Renault Trucks Master: VJX95P

Vinnumber:	VF6VF000967027436	Versionname:	Master RT 3T5 2.3 dCi 110kW FWD L3H1 Red Edition Plancher automaat
First Registrationdate:	25/03/2021	Fiscalpower:	
Expertise Mileage:	201767	Power Kw:	110
Bodytype:		Body colour:	Gris Kempenners
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Diesel	Parking lot:	1238
Number of seats:	2		
Type of rims (mounted):	Steel		
Maintenance needed:	Yes		

Options

Number of keys total	1	Telephone equipment
Manual climate control		Central consol F
Windows electric F		Rear parking sensors
Radio multimedia		

Degree of wear

225/65/16/112 R				
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6,4 mm	Re.R.	Goodyear: 7,5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.4
Tyre profile depth RR				7.5
Tyre size FL				225/65 R 16 112 R
Tyre size FR				225/65 R 16 112 R
Tyre size RL				225/65 R 16 112 R
Tyre size RR				225/65 R 16 112 R
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Armrest F M, Missing, Replace



Seat cover FL, Worn, Replace



Inner seat cover L, Missing, Replace



Seat adjuster FL, Missing, Replace



Glove compartment lid, Broken, Replace



Service, Maintenance, Execute



Ignition key, Missing, Replace

No pictures to display

Wheel cover FL, Missing, Replace



Wing FL, Scratch(es), Repair and paint (complete)



Door FL, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Outer sill L, Scratch(es), Repair and paint (partial)



Side bar L, Dent(s), Replace





Bumper F, Dent(s) and scratch(es), Replace



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Dent(s), Paintless dent repair



Wheel arch cover RR, Scratch(es), Replace



Wheel cover RR, Missing, Replace



Side bar R, Dent(s), Replace



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear view mirror housing R, Scratch(es), Replace

Outside rear-view mirror housing R, Scratch(es), Replace



Mirror side repeater R, Scratch(es), Replace



Side wall RR, Crack, Repair and paint (complete)



Boot door lining R, Crack, Replace



Bumper corner RR, Dent(s) and scratch(es), Replace



Reflector, Broken, Replace



Shutter / cover R, Deformed / Strained, Replace



Boot door panel RR, Crack, Repair and paint (complete)



Roof, Dent(s), Repair and paint (complete)

