


Vehicle details

VIN	VF73AHNS2 LJ754519	Brand	CITROEN	Maintenance date	-
Licence Plate	J5-82-KR	Model	Grand C4 SpaceTourer PureTech 130 S&S Business	Maintenance mileage	-
Registration date	31/08/2020	Year	2020	Exterior Color	Red Metallic
Odometer	186 475 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	Minivan	Next technical inspection	-
Seats	7	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	03/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Metallic paint	✓
6 seater	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 205/55/17 All seasons 3.0 mm



Michelin 205/55/17 All seasons 3.0 mm



Michelin 205/55/17 All seasons 3.5 mm

Michelin 205/55/17 All seasons 3.5 mm

Exterior

2



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3



Part	Wing
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

5



Part	Roof wind deflector
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Bumper
Position	Back
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



Part	Fuel filler flap
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



Part	Wing
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

11



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

12



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

13



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

14



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

1



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

8



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Smart Repair