



CITROEN GRD C4SPACE: FY-982-RC

Vinnumber:	VF73AYHZ4MJ666299	Versionname:	
First Registrationdate:	19/04/2021	Fiscalpower:	
Expertise Mileage:	160357	Power Kw:	
Bodytype:	MPV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Luggage cover
Number keys remote	1	Rear view camera
GPS big screen color		

Tyres

	205/55/17/95 V			
Summer tyres:	Fr.L.	Hankook: 55%	Fr.R.	Hankook: 50%
	Re.L.	Hankook: 60%	Re.R.	Hankook: 55%
Tyre profile depth FL				4.5
Tyre profile depth FR				5.0
Tyre profile depth RL				4.4
Tyre profile depth RR				4.5
Tyre size FL				205/55 R 17 95 V
Tyre size FR				205/55 R 17 95 V
Tyre size RL				205/55 R 17 95 V
Tyre size RR				205/55 R 17 95 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Malfunction indicator, Blinking, Check




Seat cover FR, Dirty, Cleaning




Tyres, No damage, Acceptable




Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Wing RL, Dent(s), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Deformed / Strained, Acceptable



Wing RR, Scratch(es), Paint



Door FR, Dent(s), Acceptable



Luggage compartment cover, Not functioning (well), Replace



Rear bulkhead lining, Scratch(es), Smart repair



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Paint

