

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	265888
License plate	1WUQ085
Vehicle identification number	VF73AYHZRKJ774046
Dossier	2019 142 144
Make	Citroen Gr.C4 SpT.1.5HDi 130 B
Mileage	131022.00
First registration	20/09/2019
	16/12/2024

CHECK POINTS

Description	Number	Present	Remark
Spare wheel		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Keys	2	Y	
Registration Part 2		N	
Repair kit		N	
RunOnFlat		N	
Charge back wrong tyres		N	
Original license plate		Y	
Towbar (+keys)		Y	
Charging cable		N	





DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
133	Bumper Rear // Painting	N
167	Roof / Roof Rails / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	N
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
203	Rocker Panel Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
641	Rear Right Door Interior Coating // Repair	Y
644	Rear Right Door Interior Coating // Replace Completely	Y


Damage Pictures




Wheel Two Tone Rear Right // Repair-scratch




Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Right // Polish-scratch




Light / Rear Right On Rear Bonnet / Replace-scratch






Bumper Rear // Painting-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Side View Mirror Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Roof / Roof Rails / Replace-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Right Door Interior Coating // Repair-scratch



Rear Right Door Interior Coating // Replace Completely-scratch





Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Painting-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent



Trunk Compartment / Boot Cover / Replace-scratch +
dent