



CITROEN BERLINGO (30)
BERLINGO M BLUEHDI 100 CLUB

VIN NO VF77BBHY6JN552110
Registration Number FC966CZ



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	228560 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2018-11-29	-

Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20251008110401
Inspection Date / Place	2025-10-08 / BCA ANGOULEME	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	4
Body Type	Box Wagon	Drive Train	Front
Seat Colour		No of Seats	3
Charging Cables		NEDC CO2 Rating (q/km)	112
Engine Rating CV	5	Metalic Colour	
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment


Central locking	Rear parking sensors	Cruise control	Radio
Electric Tailgate	Roof rails		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

5 Dommages



1 Dommages



Component	Damage	Comments
1 Cant Rail / Right	Paint / Chemical Damage	
2 Fender / Front Right	Bodywork / Dent / Deformation	
3 Front Light / Front Right	Missing Part	
4 Fender / Back Left	Bodywork / Dent / Dent	
5 Corner Bumper / Back Left	Bodywork / Assembly	
6 Door Step / Front Left	Interior / Dirty	



1. Cant Rail / Right
Paint / Chemical Damage -



2. Fender / Front Right
Bodywork / Dent / Deformation -



3. Front Light / Front Right
Missing Part -



4. Fender / Back Left
Bodywork / Dent / Dent -



5. Corner Bumper / Back Left
Bodywork / Assembly -



6. Door Step / Front Left
Interior / Dirty -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.