



CITROEN Berlingo Pkw

Berlingo Multispace VTi 95

VIN NO VF77J5FK0DJ685425
Registration Number K0DJ685425



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-09-01	1	2	167761 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-07-18	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250923135051
Inspection Date / Place	2025-09-23 / BCA Oberndorf	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	White	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	4
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	155
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Front fog lamps	Remote central locking
Radio	Alloys wheels	Cruise control	Remote adjusting wing mirrors
Stability control	Rear parking sensors		

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	16
------------------	-----	------------------	----

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	7
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

12 Schäden



11 Schäden




Component		Damage	Comments
1	Rim / Front Right	Out of Bodywork / Scratch	
2	Windshield / Front	Glass Break / Impact	
3	Seat / Front Right	Interior / Worn - out	
4	Panel Filling / Front Right	Interior / Scratched	
5	Roof Upholstery	Interior / Scratched	
6	Panel Filling / Front Left	Interior / Dirty	
7	Panel Filling / Front Left	Interior / Scratched	
8	Ignition Key	Interior / Not Working	
9	Floor Carpet	Interior / Holed	
10	Seat / Front Left	Interior / Holed	
11	Gear Knob	Interior / Scratched	
12	Steering Wheel / Front	Interior / Worn - out	

13	Cabin	Interior / Scraped
14	Door / Front Left	Bodywork / Dent / Dent
15	Door Joint / Front Left Middle	Bodywork / Breakage / Crack
16	Door Slide / Left	Paint / Poor Previous Repair
17	Windshield / Front	Glass Break / Impact
18	Hood	Paint / Poor Previous Repair
19	Door Slide / Right	Paint / Poor Previous Repair
20	Trunk Tailgate Handle / Back	Bodywork / Breakage / Crack
21	Front Light / Front Left	Glass Break
22	Roof	Paint / Poor Previous Repair
23	Tailgate	Paint / Scratch / Scuff



1. Rim / Front Right
Out of Bodywork / Scratch -




2. Windshield / Front
Glass Break / Impact -



3. Seat / Front Right
Interior / Worn - out -



4. Panel Filling / Front Right
Interior / Scratched -



5. Roof Upholstery
Interior / Scratched -



6. Panel Filling / Front Left
Interior / Dirty -




7. Panel Filling / Front Left
Interior / Scratched -



8. Ignition Key
Interior / Not Working -



9. Floor Carpet
Interior / Holed -




10. Seat / Front Left
Interior / Holed -



11. Gear Knob
Interior / Scratched -



12. Steering Wheel / Front
Interior / Worn - out -



13. Cabin
Interior / Scraped -




14. Door / Front Left
Bodywork / Dent / Dent -



15. Door Joint / Front Left Middle
Bodywork / Breakage / Crack -



16. Door Slide / Left
Paint / Poor Previous Repair -




17. Windshield / Front
Glass Break / Impact -



18. Hood
Paint / Poor Previous Repair -



19. Door Slide / Right
Paint / Poor Previous Repair -




20. Trunk Tailgate Handle / Back
Bodywork / Breakage / Crack -



21. Front Light / Front Left
Glass Break -



22. Roof
Paint / Poor Previous Repair -



23. Tailgate
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Service Light	⚠

Equipments Test

Central Locking	⚠	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
Clutch			
Clutch Functioning	✓		
General			
Test Driven Status	Not Performed		
✓	No troubles detected, good condition or correct tests, according to vehicle age and mileage		
ⓘ	Damages or malfunction detected that requires repairs by the buyer		
NA	Not applicable		
☐	Not tested		

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)