



Citroen Berlingo: 1RVD658

Vinnumber:	VF77J5FK6GJ905833	Versionname:	Berlingo Break Live 1.6VTi 98pk/cv 4p
First Registrationdate:	9/03/2017	Fiscalpower:	
Expertise Mileage:	27324	Power Kw:	72
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	-4100km		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	N.A.		

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 94 H
Tyre size RL				195/65 R 15 94 H
Tyre size RR				195/65 R 15 94 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	No	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Ignition key, Broken, Replace



Roof liner, Dirty, Cleaning



Steering wheel, Worn, Acceptable



Gear shift lever knob, Worn, Acceptable



Floor covering R, Damaged, Replace



Bumper F, Dent(s) and scratch(es), Replace



Bumper moulding F, Scratch(es), Replace



Bumper grille, Scratch(es), Acceptable



Door seal FL, Broken, Replace



Outside rear-view mirror housing L, Scratch(es), Acceptable



Mirror side repeater L, Broken, Replace



Wing FL, Dent(s), Acceptable



Spare wheel, Missing, Check



Boot door lining L, Missing, Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Acceptable



Door seal RR, Broken, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door seal FR, Broken, Replace



Roof, Dent(s), Paintless dent repair

