

Inspection Protocol



CITROEN BERLINGO MULTISPACE 1.6 BLUEHDI 100 8V

Vehicle information

License plate	OAC324	Inspected by	A.H.
Year model	2015	Date of inspection	2025-04-10
Manuf. year/month	2015-05	City	Falkenberg
First day in traffic	2015-06	Keys	1
Colour	Blå	Service book	Saknas
Mileage	150 320 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	Manuell	Summer tires	15" alu-fälg 3/3/2/3
Engine effect	73 kW	Winter tires	alu-fälg dubbat 2/3/4/4

Damages

Location	Damage	Comments	Costs excluding VAT
Other, Other	Other	Sliten ratt	-
Door, Left sliding door	Scratches below 30 mm	Lack släpp dörr spåret	70 €
Bumper, Rear	Cargo scratches		180 €
Door, Right side mirror	Paint retouch traces		10 €
Bumper, Front	Wide scratch		300 €
Glass, Windshield	Cracks small (max 30 mm)		270 €
Rims & Tires, Unevenly worn/Wheels unaligned	Snedsliitna/Hjulinställning	Bak	140 €
Rims & Tires, Winter	1 tire below 3 mm		140 €
Rims & Tires, Summer	1 tire below 3 mm		140 €
Keys	Extra key missing		230 €
Keys	Other	Trasig fjärr	-
Engine and Transmission, Motor	Noise	Lite klonkade ljud vid start	-

Total excl. VAT	1 480 €
------------------------	----------------

Service occasions

6500-MIL, 8000-MIL, 11000-MIL

Images

[See all images in large format](#)















Nycklar Övrigt Trasig fjärr



Övrigt Övrigt Övrigt Sliten ratt



Dörr Vänster skjutdörr Repor under 3 cm Lack släpp dörr spåret 800 kr



Stötfångare Bak Lastrepor 2 000 kr



Dörr Höger backspegel Lackbättring 50 kr



Stötfångare Fram Skrap 3 300 kr



Glas Vindruta Sprickor små (max 3 cm) 3 000 kr







Fälgar & Däck Snedslitna/Hjulinställning Snedslitna/Hjulinställning Bak 1 500 kr