



CITROEN NEMO: EH-099-RY

Vinnumber:	VF7AAFHY5GS164006	Versionname:	
First Registrationdate:	20/12/2016	Fiscalpower:	
Expertise Mileage:	219438	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1
Number keys remote	1

Tyres

	185/65/15/88 H			
Summer tyres:	Fr.L.	Kleber: 40%	Fr.R.	Kleber: 45%
	Re.L.	Michelin: 25%	Re.R.	Michelin: 30%
Tyre profile depth FL	5.6			
Tyre profile depth FR	5.3			
Tyre profile depth RL	6.4			
Tyre profile depth RR	6.3			
Tyre size FL	185/65 R 15 88 H			
Tyre size FR	185/65 R 15 88 H			
Tyre size RL	185/65 R 15 88 H			
Tyre size RR	185/65 R 15 88 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	2479			
Tyre make FR	2479			
Tyre make RL	261			
Tyre make RR	261			

Assistance equipment

Spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Malfunction indicator, Blinking, Check



Floor mat F, Tear, Replace



Inner door sill FL, Scratch(es), Paint



Air vent, mid-dashboard, Broken, Replace



Air vent, mid-dashboard, Broken, Replace



Air vent L, Broken, Replace



Seat cover FR, Stain, Cleaning



Tyres, No damage, Acceptable



Steel rim FR, Deformed / Strained, Replace



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Outside rear-view mirror base L, Scratch(es), Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Replace



Side wall RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FR, Deformed / Strained, Replace



Wing FR, Dent(s), Repair and paint (complete)



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Replace



Partition wall, Bad repair, Replace



Load compartment roof, Dent(s), Repair and paint (complete)



Bodywork, Not original part, Acceptable

