



CITROEN BERLINGO

Berlingo 1.6 HDi 75

VIN NO VF7GJ9HWC93456716
Registration Number FT859JN



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	284876 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2007-06-18	-

Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251001113421
Inspection Date / Place	2025-10-01 / BCA BOUCHAIN	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	140

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warranty			



Equipment


Central locking	Power assisted steering	Front fog lamps
-----------------	-------------------------	-----------------

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

10 Dommages



0 Dommages



Component		Damage	Comments
1	Fender / Front Left	Bodywork / Dent / Deformation	
2	Mirror / Front Left	Bodywork / Dent / Deformation	
3	Back Light / Left	Glass Break / Impact	
4	Bumper / Back	Bodywork / Dent / Deformation	
5	Fender / Back Right	Bodywork / Dent / Deformation	
6	Door / Back Right	Bodywork / Dent / Deformation	
7	Door / Front Right	Bodywork / Dent / Deformation	
8	Fender / Front Right	Bodywork / Dent / Deformation	
9	Corner Bumper / Front Right	Paint / Scratch / Line	
10	Corner Bumper / Front Right	Paint / Scratch / Line	



1. Fender / Front Left
Bodywork / Dent / Deformation -



2. Mirror / Front Left
Bodywork / Dent / Deformation -



3. Back Light / Left
Glass Break / Impact -



4. Bumper / Back
Bodywork / Dent / Deformation -



5. Fender / Back Right
Bodywork / Dent / Deformation -



6. Door / Back Right
Bodywork / Dent / Deformation -



7. Door / Front Right
Bodywork / Dent / Deformation -



8. Fender / Front Right
Bodywork / Dent / Deformation -



9. Corner Bumper / Front Right
Paint / Scratch / Line -



10. Corner Bumper / Front Right
Paint / Scratch / Line -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.