

Vehicle details

VIN	VF7PSCFB5 KR535021	Brand	Citroën	Maintenance date	-
Licence Plate	H6-80-HG	Model	C1 VTi 72 S;S Feel 5d	Maintenance mileage	-
Registration date	31/01/2020	Year	2020	Exterior Color	White Solid
Odometer	132 879 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	19/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Key	✓
Remote key	✓

Tyres

Continental 165/65/14 Summer 6.0 mm	Continental 165/65/14 Summer 6.0 mm
Continental 165/65/14 Summer 6.5 mm	Continental 165/65/14 Summer 6.5 mm

Exterior

1		Part: Door Position: Back left Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair	2		Part: Wing Position: Back right Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Repair
3		Part: Bumper Position: Back Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	4		Part: Bumper Position: Front right Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Repair

5



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair