

Vehicle details

VIN	VF7PSCFB7 LR553418	Brand	Citroën	Maintenance date	-
Licence Plate	J6-43-LX	Model	C1 VTi 72 S;S ActieAuto 5d Feel APL	Maintenance mileage	-
Registration date	17/09/2020	Year	2020	Exterior Color	White Solid
Odometer	84 960 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	17/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Goodyear 165/60/15 Summer 3.5 mm	Goodyear 165/60/15 Summer 2.5 mm
Continental 165/60/15 Summer 6.0 mm	Continental 165/60/15 Summer 6.0 mm

Exterior

2



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair


3



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

1



Part	Interior cleaning
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning