

Vehicle details

VIN	VF7PSCFB7 LR554424	Brand	Citroën	Maintenance date	-
Licence Plate	K4-58-BR	Model	C1 VTi 72 S;S Feel 5d	Maintenance mileage	-
Registration date	25/11/2020	Year	2020	Exterior Color	White Solid
Odometer	91 299 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	15/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres



Exterior

2		Part	Door	3		Part	Sill
		Position	Front left			Position	Left
4		Damages	Dented	5		Damages	Dent & Chips
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Repair
		Part	Door			Part	Step plate
		Position	Back left			Position	Front right
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	-
		Repair mode	Smart Repair			Repair mode	For info

6



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

7



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●

8



Part	Bonnet
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●●●

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning