

CITROEN C3 C3 BlueHDi 100 S&S BVM6 Shine



VIN NO VF7SXYHTUNT542777 Registration Number GF516DX

MOT Date

Number of Owners

Number of Keys

Odometer Reading

╈-

:2: -

P1

65908 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

#-

23-

2022-03-14

e

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250828094031
Inspection Date / Place	2025-08-28 / BCA AUNAY	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1499
Engine Size	1.5	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			

























Equipment

Sunroof Type

Central locking	Radio	Stability control	Front fog lamps	
Electrically folding wing mirrors	Rear parking sensors	Cruise control	Satellite navigation	
Equipment Details				
Equipment Details				

Tilt/Slide Steel

Cosmetic Damage



	Component	Damage	Comments
1	Seat / Back Center	Interior / Missing	
2	Side Window / Front Left	Glass Break	
3	Fender / Back Right	Bodywork / Dent / Dent	
4	Corner Bumper / Back Right	Paint / Scratch / Line	
5	Door / Back Right	Paint / Scratch / Line	



1. Seat / Back Center Interior / Missing -

2. Side Window / Front Left Glass Break -



3. Fender / Back Right Bodywork / Dent / Dent -

4. Corner Bumper / Back Right Paint / Scratch / Line -



5. Door / Back Right Paint / Scratch / Line -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut



- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.