

## GENERAL INFO

File	280757
License plate	26506
VIN	VF7VAYHVKKZ061524
Dossier	2019 126 271 / 241258
Make / Model	Citroen Jumpy Com. 1.5HDI XL 120 Comf.
Mileage	96843
1st inscription	21/06/2019
Start from	
Available from	9/07/2024

## CHECK POINTS

Description	Number	Pres	Remark
Original license plate	0		
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)			
Certificate of conformity			
Registration certificate Part 1			
Repair kit			
RunOnFlat			
Charging cable			



## DAMAGES

Id	Damage	Dossier nbr	Acceptable damage
<b>OTHER DAMAGE(S)</b>			
35	Front Bonnet // Polish		Y
41	Windshield // Replace		Y
66	Wing Front Left // Polish		Y
196	Door Rear Right // Polish		Y
<b>DAMAGE 224.249.411</b>			
19	Bumper Front / Lower Cover Not Painted / Replace	224.249.411	N
183	Wing Rear Right // Painting	224.249.411	N
231	Wing Front right // Smart Repair Medium	224.249.411	N
301	Rear Loading Door Right // Smart Repair Medium	224.249.411	N
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	224.249.411	N
881	Key Price Range 1 //	224.249.411	N

**If any missing items (keys, accessories, car documents, etc.) are invoiced you still can return them to Arval within five business days after reception of the inspection report. You may send this by registered letter to / return it on site ( Arval Belgium NV/SA, Ikaroslaan 99, 1930 Zaventem ) .**

DAMAGE PICTURES



Damage within Renta-norm

**DAMAGE 1**



Bumper Front / Lower Cover Not Painted / Replace: E - Scratch



Wing Front right // Smart Repair Medium: E - Scratch

**OTHER DAMAGES**





Front Bonnet // Polish: E - Scratch




Windshield // Replace: E - Scratch





Wing Front Left // Polish: E - Scratch



Wing Rear Right // Painting: E - Scratch



Door Rear Right // Polish: E - Scratch



Rear Loading Door Right // Smart Repair Medium: A - Dent



Trunk Lid Interior Coating / MDF Rear Left / Replace: C - Hole

Key Price Range 1 //: R - Missing