

## GENERAL INFO

File	280757
License plate	26744
VIN	VF7VAYHVKKZ077635
Dossier	2019 126 562 / 241516
Make / Model	Citroen Jumpy Com. 1.5HDI XL 120 Comf.
Mileage	107106
1st inscription	8/11/2019
Start from	
Available from	11/07/2024

## CHECK POINTS

Description	Number	Pres	Remark
Original license plate		Y	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)			
Certificate of conformity	0	Y	kluis arval
Registration certificate Part 1	0	Y	kluis arval
Repair kit			
RunOnFlat			
Charging cable			



## DAMAGES

Id	Damage	Dossier nbr	Acceptable damage
<b>OTHER DAMAGE(S)</b>			
40	Windshield // Repair		Y
210	Door Front Right // Smart Repair Small		Y
860	Interior Cleaning // Small		Y
<b>DAMAGE 222.152.089</b>			
422	Seat Front Right / Bottom Coating / Replace	222.152.089	N
<b>DAMAGE 224.260.095</b>			
17	Bumper Front // Replace without painting	224.260.095	N
63	Wing Front Left // Painting	224.260.095	N
83	Door Front Left // Painting	224.260.095	N
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	224.260.095	N

**If any missing items (keys, accessories, car documents, etc.) are invoiced you still can return them to Arval within five business days after reception of the inspection report. You may send this by registered letter to / return it on site ( Arval Belgium NV/SA, Ikaroslaan 99, 1930 Zaventem ) .**

DAMAGE PICTURES



Damage within Renta-norm

**DAMAGE 1**





Bumper Front // Replace without painting: E - Scratch




Wing Front Left // Painting: E - Scratch

**OTHER DAMAGES**




Windshield // Repair: D - Broken




Door Front Left // Painting: AB - Bad repair




Door Front Right // Smart Repair Small: AA - Scratch +Dent



Seat Front Right / Bottom Coating / Replace: J - Incinerated



Trunk Lid Interior Coating / MDF Rear Left / Replace: C - Hole



Interior Cleaning // Small: U - Filthy