

GENERAL INFO

| | |
|-----------------|--|
| File | 280757 |
| License plate | 26703 |
| VIN | VF7VAYHVKKZ078470 |
| Dossier | 2019 126 442 / 241275 |
| Make / Model | Citroen Jumpy Com. 1.5HDI XL 120 Comf. |
| Mileage | 91318 |
| 1st inscription | 18/10/2019 |
| Start from | |
| Available from | 9/07/2024 |

CHECK POINTS

| Description | Number | Pres | Remark |
|---------------------------------|--------|------|--------|
| Original license plate | 0 | | |
| Keys | 2 | Y | |
| Spare wheel | | Y | |
| Towbar (+keys) | | | |
| Certificate of conformity | | | |
| Registration certificate Part 1 | | | |
| Repair kit | | | |
| RunOnFlat | | | |
| Charging cable | | | |






DAMAGES

| Id | Damage | Dossier nbr | Acceptable damage |
|---------------------------|---|-------------|-------------------|
| OTHER DAMAGE(S) | | | |
| 35 | Front Bonnet // Polish | | Y |
| 124 | Light / Rear left / Replace | | Y |
| 533 | Trunk Compartment / Side Cover Right / Replace | | Y |
| 593 | Trunk Lid Interior Coating / MDF Rear Right / Replace | | Y |
| DAMAGE 222.054.316 | | | |
| 13 | Bumper Front // Painting | 222.054.316 | N |
| 194 | Door Rear Right // Repair & Painting | 222.054.316 | N |
| 214 | Door Front Right // Repair & Painting | 222.054.316 | N |
| 234 | Wing Front right // Repair & Painting | 222.054.316 | N |
| DAMAGE 224.225.182 | | | |
| 183 | Wing Rear Right // Painting | 224.225.182 | N |
| 201 | Rocker Panel Right // Smart Repair Medium | 224.225.182 | N |
| 452 | Seat Rear Right / Bottom Coating / Replace | 224.225.182 | N |
| 532 | Trunk Compartment / Side Cover Left / Replace | 224.225.182 | N |

If any missing items (keys, accessories, car documents, etc.) are invoiced you still can return them to Arval within five business days after reception of the inspection report. You may send this by registered letter to / return it on site (Arval Belgium NV/SA, Ikaroslaan 99, 1930 Zaventem) .

DAMAGE PICTURES





Damage within Renta-norm


DAMAGE 1



Bumper Front // Painting: E - Scratch



Door Rear Right // Repair & Painting: AA - Scratch +Dent



Door Front Right // Repair & Painting: AA - Scratch +Dent




Wing Front right // Repair & Painting: AA - Scratch +Dent


OTHER DAMAGES




Front Bonnet // Polish: E - Scratch



Light / Rear left / Replace: E - Scratch




Wing Rear Right // Painting: E - Scratch



Rocker Panel Right // Smart Repair Medium: AA - Scratch +Dent



Seat Rear Right / Bottom Coating / Replace: J - Incinerated



Trunk Compartment / Side Cover Left / Replace: D - Broken



Trunk Compartment / Side Cover Right / Replace: R - Missing



Trunk Lid Interior Coating / MDF Rear Right / Replace: R - Missing