

Inspection Protocol



CITROEN JUMPY VAN IP 2.0 BLUEHDI 120 EAT, 122HK, 2021

Vehicle information

License plate	TMR68L	Inspected by	C.C.
Year model	2021	Date of inspection	2025-04-14
Manuf. year/month	2021-01	City	Björkvik
First day in traffic	2021-01	Keys	2
Colour	Vit	Service book	Ja
Mileage	152 360 km	Latest service	2025-02-24
Fuel	Diesel	Mileage at the latest service	151 230 km
Transmission	Automat	Summer tires	16" plåtfälg 4/4/4/4
Engine effect	90 kW	Winter tires	plåtfälg dubbat 3/3/3/3

Damages

Location	Damage	Comments	Costs excluding VAT
Wing, Rear left	Dent above 100 mm		400 €
Bumper, Rear	Cargo scratches		180 €
Door, Front right	Dents below 30 mm		70 €
Door, Front right	Scratches 30-100 mm		100 €
Bumper, Front	Cracks 30 mm-100 mm		300 €

Total excl. VAT	1 050 €
-----------------	---------

Images

[See all images in large format](#)





















Skärm Vänster bak Bucklor över 10 cm 4 400 kr



Stötfångare Bak Lastrepor 2 000 kr





Dörr Höger fram Bucklor under 3 cm 800 kr



Dörr Höger fram Repor 3-10 cm 1 100 kr



Stötfångare Fram Sprickor, 3-10 cm 3 300 kr





