



Citroen Jumper (Segm. B3): 1UDF176

Vinnumber:	VF7YB2MFA12G73148	Versionname:	Jumper Club 33 L1H2 2.0BlueHDi 131pk/cv
First Registrationdate:	5/04/2018	Fiscalpower:	
Expertise Mileage:	47050	Power Kw:	96
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	plus 35530 km		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	N.A.		

Tyres

225/70/15/110 R				
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				7.0
Tyre size FL				225/70 R 15 110 R
Tyre size FR				225/70 R 15 110 R
Tyre size RL				225/70 R 15 110 R
Tyre size RR				225/70 R 15 110 R
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Missing, Replace



Ignition key, Missing, Replace



Ignition key, Broken, Replace



Steering wheel, Scratch(es), Acceptable




Interior, Stain, Cleaning



Door panel RR, Broken, Replace



Door panel RL, Broken, Replace



Bonnet, Not original part, Acceptable



Outside rear-view mirror housing L, Scratch(es), Replace



Door trim FL, Missing, Replace



Step L, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Acceptable



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Mirror side repeater L, Scratch(es), Replace



Wheel aperture RL, Dent(s) and scratch(es), Spot repair



Wheel aperture RR, Dent(s) and scratch(es), Spot repair



Boot door lining R, Scratch(es), Acceptable



Boot door lining L, Scratch(es), Replace



Tailgate handle, Broken, Replace



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Rear light L, Scratch(es), Replace



Boot door panel RL, Dent(s), Acceptable



Bumper R, Scratch(es), Replace




Door trim FR, Missing, Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Step R, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Bodywork, Damaged, Acceptable



