



# TOYOTA Yaris

## Yaris Hybrid 1.5 VVT-i

VIN NO VNKKD3D330A591767  
Registration Number 330A591767



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| 2026-05-01   | 1                    | 2                       | 132510 km                |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| 2025-03-04   | 122905               | 2019-05-24              | Germany                  |

### Inspection Report Summary

|                         |                                          |                |                 |
|-------------------------|------------------------------------------|----------------|-----------------|
| Customer                | BCA Online                               | Report Number  | P20250908133903 |
| Inspection Date / Place | 2025-09-08 / ARS Altmann<br>AG Riedstadt | Cosmetic Grade | 4               |

### Vehicle Summary




|                    |                                |                        |        |
|--------------------|--------------------------------|------------------------|--------|
| Vehicle Condition  | Runner                         | VAT Type               | Margin |
| Fuel Type          | Hybrid Electric Vehicle Petrol | Road Worthy            | Yes    |
| Colour             | Black                          | Engine Size (cc)       | 1497   |
| Engine Size        | 1.5                            | No of Doors            | 5      |
| Body Type          | Sedan                          | Drive Train            | Front  |
| Seat Colour        |                                | No of Seats            | 5      |
| Seat Covering Name |                                | Seat Covering          | Cloth  |
| Charging Cables    |                                | NEDC CO2 Rating (q/km) | 84     |
| Gearbox Type       | Automatic                      |                        |        |

### Vehicle History & Documents

|                        |                      |                      |    |
|------------------------|----------------------|----------------------|----|
| Service Book Available | Full Service History | Next Service Mileage | km |
| Previous Usage         |                      | Imported             | No |
| Manufacturer Warrenty  |                      |                      |    |







Equipment

|                               |                       |                               |                        |
|-------------------------------|-----------------------|-------------------------------|------------------------|
| Tinted Glass                  | Trip Computer         | Airbag Status                 | Anti-lock braking      |
| Bluetooth telephone interface | Front fog lamps       | Highbeamassist                | Remote central locking |
| Split folding rear seats      | Distancewarningsystem | Laneassist                    | Radio                  |
| Tow ball                      | USB Socket            | Alloys wheels                 | Auxiliary Socket       |
| Cruise control                | Heated wing mirrors   | Remote adjusting wing mirrors | Reversing Camera       |
| Stability control             | Keyless Entry         | Leather steering wheel        |                        |

Equipment Details


|                  |            |                        |                           |
|------------------|------------|------------------------|---------------------------|
| Tow Ball Type    | Detachable | Air Conditioning       | Dual Zone Climate Control |
| Alloy Wheel Size | 15         | Extra Wheel / Tyre Set | Winter Tyres - Alloy      |
| Seat Heating     | Front      |                        |                           |

Wheels & Tyres

|                            |   |                            |   |
|----------------------------|---|----------------------------|---|
| Right Front Tyre Depth     | 6 | Left Front Tyre Depth      | 6 |
| Right Rear Tyre Depth      | 6 | Left Rear Tyre Depth       | 6 |
| Extra Wheel - 1 Tyre Depth | 6 | Extra Wheel - 2 Tyre Depth | 6 |
| Extra Wheel - 3 Tyre Depth | 7 | Extra Wheel - 4 Tyre Depth | 7 |

Cosmetic Damage


8 Schäden



0 Schäden



| Component                 | Damage                    | Comments |
|---------------------------|---------------------------|----------|
| 1 Bumper / Front          | Paint / Scratch / Scuff   |          |
| 2 Door / Front Right      | Paint / Scratch / Scuff   |          |
| 3 Side Panel / Back Right | Paint / Scratch / Scuff   |          |
| 4 Side Panel / Back Right | Bodywork / Dent / Dent    |          |
| 5 Side Panel / Back Left  | Bodywork / Dent / Dent    |          |
| 6 Door / Back Left        | Paint / Scratch / Scuff   |          |
| 7 Door / Front Left       | Paint / Scratch / Scuff   |          |
| 8 Rim / Front Left        | Out of Bodywork / Scratch |          |



1. Bumper / Front  
Paint / Scratch / Scuff -




2. Door / Front Right  
Paint / Scratch / Scuff -



3. Side Panel / Back Right  
Paint / Scratch / Scuff -




4. Side Panel / Back Right  
Bodywork / Dent / Dent -



5. Side Panel / Back Left  
Bodywork / Dent / Dent -



6. Door / Back Left  
Paint / Scratch / Scuff -



7. Door / Front Left  
Paint / Scratch / Scuff -



8. Rim / Front Left  
Out of Bodywork / Scratch -

## Mechanical Condition

### Control Lights

|                      |   |                                              |   |
|----------------------|---|----------------------------------------------|---|
| Display Defect       | ✓ | Service Light                                | ✓ |
| ABS Warning Light    | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light | ✓ | Oil Pressure Warning Light                   | ✓ |
| Brake Warning Light  | ✓ | Power Steering Warning Light                 | ✓ |
| Alternator / Battery | ✓ | No Dashboard Lights                          | ✓ |

### Hybrid/EV

|                     |   |
|---------------------|---|
| Hybrid System Fault | ✓ |
|---------------------|---|

### Equipments Test

|                     |   |                                       |   |
|---------------------|---|---------------------------------------|---|
| Other Equipments    | ✓ | Central Locking                       | ✓ |
| Electric Windows    | ✓ | Parking Sensors / Cameras Functioning | ✓ |
| AC / Heating System | ✓ |                                       |   |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Starts       | ✓ | Engine Status / EML | ✓ |
| Engine Leak Visible | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

## Test Drive Inspection

| Steering Wheel                                                                                       |   |                                               |   |
|------------------------------------------------------------------------------------------------------|---|-----------------------------------------------|---|
| Steering   Noise / Anomaly                                                                           |   | ✓                                             |   |
| Engine                                                                                               |   |                                               |   |
| Engine Noise                                                                                         | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| Fume Quantity                                                                                        | ✓ | Power Loss                                    | ✓ |
| Brake                                                                                                |   |                                               |   |
| Brake System Anomaly                                                                                 |   | ✓                                             |   |
| General                                                                                              |   |                                               |   |
| Test Driven Status                                                                                   |   | ✓                                             |   |
| ✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i> |   |                                               |   |
| ! <i>Damages or malfunction detected that requires repairs by the buyer</i>                          |   |                                               |   |
| NA <i>Not applicable</i>                                                                             |   |                                               |   |
| = <i>Not tested</i>                                                                                  |   |                                               |   |

## Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)