


Vehicle details

VIN	VNVK14001 65962519	Brand	NISSAN	Maintenance date	-
Licence Plate	J6-44-SZ	Model	MICRA IG-T 100 ActieAuto Xtronic 5d N-Connecta APL	Maintenance mileage	-
Registration date	16/10/2020	Year	2020	Exterior Color	Black Metallic
Odometer	86 358 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		


Inspection Details

Inspection date	17/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment	Removable element	Technical Document
Manual air-conditioning ✓	Spare wheel kit ✓	User manual ✓
Cruise control ✓	Rear parcel shelf ✓	Warranty booklet ✓
GPS system ✓		Spare key ✓
Alloy wheel rims ✓		Remote key ✓
Automatic Gearbox ✓		Sat Nav CD ROM Software ✓
Central locking ✓		
Electric windows ✓		
Audio System ✓		

Tyres



Exterior

<p>1</p>  <p>● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Door	Position	Back left	Damages	Dent & Chips	Severity	-	Repair mode	Repair	<p>2</p>  <p>● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Wing	Position	Back left	Damages	Dent & Chips	Severity	-	Repair mode	Repair
Part	Door																						
Position	Back left																						
Damages	Dent & Chips																						
Severity	-																						
Repair mode	Repair																						
Part	Wing																						
Position	Back left																						
Damages	Dent & Chips																						
Severity	-																						
Repair mode	Repair																						
<p>3</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </tbody> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair												
Part	Bonnet																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						