


Vehicle details

VIN	VNVK14002 64778762	Brand	NISSAN	Maintenance date	-
Licence Plate	H7-33-HR	Model	MICRA IG-T 100 Business Edition 5d	Maintenance mileage	-
Registration date	11/02/2020	Year	2020	Exterior Color	Black Solid
Odometer	120 546 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	22/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✗






Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓


Tyres



Exterior

2		<table border="0"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Front right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	3		<table border="0"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Wing																								
Position	Front right																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
Part	Bonnet																								
Position	-																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
4		<table border="0"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	5		<table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front left	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Bumper																								
Position	Front																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
Part	Door																								
Position	Front left																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
6		<table border="0"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair													
Part	Bumper																								
Position	Back																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								

Interior damage

1		<table border="0"> <tr><td>Part</td><td>Rear parcel shelf</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Rear parcel shelf	Position	-	Damages	Missing	Severity	-	Repair mode	Replace
Part	Rear parcel shelf											
Position	-											
Damages	Missing											
Severity	-											
Repair mode	Replace											