

Vehicle details

VIN	VNVK14006 65620368	Brand	NISSAN	Maintenance date	-
Licence Plate	J3-62-HH	Model	MICRA IG-T 100 ActieAuto 5d Acenta APL	Maintenance mileage	-
Registration date	05/08/2020	Year	2020	Exterior Color	Beige Laque
Odometer	67 329 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	06/08/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Bridgestone 195/55/16 Summer 3.5 mm		Bridgestone 195/55/16 Summer 2.5 mm	
Michelin 195/55/16 Summer 4.5 mm		Bridgestone 195/55/16 Summer 4.5 mm	

Exterior

2		Part	Step plate
		Position	Front left
		Damages	Dented
		Severity	-
		Repair mode	For info
3		Part	Step plate
		Position	Back left
		Damages	Dented
		Severity	-
		Repair mode	For info

5



Part	Tailgate / Boot door
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

● ● ●

6



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

● ● ● ●

7



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

● ●

8



Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

● ●

9



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

● ●

10



Part	Sill
Position	Right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

● ●

Interior damage

1



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

●●●●●

4



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

●●●●●