


Vehicle details

VIN	VNVK14007 60900054	Brand	NISSAN	Maintenance date	-
Licence Plate	TD-01-7S	Model	MICRA IG-T 90 ActieAuto 5d N-Connecta APL	Maintenance mileage	-
Registration date	18/07/2018	Year	2018	Exterior Color	Grey Metallic
Odometer	107 511 km	Engine size	898	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓


Technical Document

Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 195/55/16 Summer 4.5 mm	Continental 195/55/16 Summer 5.0 mm
Bridgestone 195/55/16 Summer 6.0 mm	Bridgestone 195/55/16 Summer 6.0 mm

Exterior

1		Part Position Damages Severity Repair mode	Roof wind deflector Centre Dent & Chips Diameter (mm) > 20 Repair	2		Part Position Damages Severity Repair mode	Roof - Dent & Chips Diameter (mm) > 20 Repair
3		Part Position Damages Severity Repair mode	Windscreen - Broken - Replace	4		Part Position Damages Severity Repair mode	Bonnet - Dent & Chips Diameter (mm) > 20 Repair
5		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair	6		Part Position Damages Severity Repair mode	Wing Front right Dent & Chips Diameter (mm) > 20 Repair
7		Part Position Damages Severity Repair mode	Door Front right Dented Diameter (mm) > 20 Smart Repair	8		Part Position Damages Severity Repair mode	Door Back right Dent & Chips Diameter (mm) > 20 Repair
9		Part Position Damages Severity Repair mode	Wing Back right Dented Diameter (mm) > 20 Smart Repair	10		Part Position Damages Severity Repair mode	Roof post A/B/C Right Dent & Chips Diameter (mm) > 20 Repair
11		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair	12		Part Position Damages Severity Repair mode	Tailgate / Boot door Back Dent & Chips Diameter (mm) > 20 Repair
13		Part Position Damages Severity Repair mode	Door Back left Dented Diameter (mm) > 20 Smart Repair	14		Part Position Damages Severity Repair mode	Door Front left Dented Diameter (mm) > 20 Smart Repair
15		Part Position Damages Severity Repair mode	Wing Front left Dented Diameter (mm) > 20 Smart Repair	16		Part Position Damages Severity Repair mode	Alloy wheel 16" Front left Scratched - Lumpsum repair

19



Part	Roof post A/B/C
Position	Left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

20



Part	Alloy wheel 16"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair


Interior damage

17



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

18



Part	Fabric seat
Position	Front left
Damages	Burnt
Severity	-
Repair mode	Smart Repair