


Vehicle details

VIN	VNVK14007 63840100	Brand	NISSAN	Maintenance date	-
Licence Plate	G2-77-HF	Model	MICRA IG-T 100 Business Edition 5d	Maintenance mileage	-
Registration date	25/09/2019	Year	2019	Exterior Color	Black Metallic
Odometer	135 170 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 195/55/16 Summer 4.0 mm		Continental 195/55/16 Summer 4.0 mm		Continental 195/55/16 Summer 9.0 mm
Bridgestone 195/55/16 Summer 5.5 mm		Bridgestone 195/55/16 Summer 5.5 mm		

Exterior

1



PartDoor

PositionFront left

DamagesDented

SeverityNumber > 2

Repair modeSmart Repair

2



PartRoof

Position-

DamagesDent & Chips

Severity-

Repair modeRepair

3



PartBonnet

Position-

DamagesDent & Chips

Severity-

Repair modeRepair

4



PartBumper

PositionFront

DamagesScratched

Severity-

Repair modeRepair

5



PartWing

PositionFront left

DamagesDent & Chips

Severity-

Repair modeRepair

6



PartAlloy wheel 16"

PositionFront left

DamagesScratched

Severity-

Repair modeLumpsum repair

7



PartDoor

PositionBack left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

8



PartWing

PositionBack left

DamagesDent & Chips

Severity-

Repair modeRepair

9



PartAlloy wheel 16"

PositionBack left

DamagesScratched

Severity-

Repair modeLumpsum repair

10



PartTailgate / Boot door

PositionBack

DamagesDent & Chips

Severity-

Repair modeRepair

11



PartBumper

PositionBack

DamagesScratched

Severity-

Repair modeRepair

12



PartDoor

PositionBack right

DamagesDent & Chips

Severity-

Repair modeRepair

13



PartDoor

PositionFront right

DamagesDent & Chips

Severity-

Repair modeRepair

15



PartWing


PositionFront right

DamagesDent & Chips

Severity-

Repair modeRepair

16



PartAlloy wheel 16"

PositionFront right

DamagesScratched

Severity-

Repair modeLumpsum repair

Interior damage

14



Part	Rear-view mirror base plate interior lining
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair