

Vehicle details

VIN	VNVK14009 60626761	Brand	NISSAN	Maintenance date	-
Licence Plate	ST-73-9N	Model	MICRA IG-T 90 ActieAuto 5d N-Connecta APL	Maintenance mileage	-
Registration date	05/06/2018	Year	2018	Exterior Color	White Solid
Odometer	70 293 km	Engine size	898	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	10/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 195/55/16 Summer 2.0 mm		Pirelli 195/55/16 Summer 3.0 mm	
Continental 195/55/16 Summer 4.0 mm		Continental 195/55/16 Summer 4.0 mm	

Exterior

1



Part

Position

Damages

Severity

Repair mode

Wing

Front left

Scratched

Length (cm) > 10

Repair

2



Part

Position

Damages

Severity

Repair mode

Alloy wheel 16"

Front left

Scratched

-

Lumpsum repair

3



Part

Position

Damages

Severity

Repair mode

Door

Front left

Dented

Diameter (mm) > 20

Smart Repair

5



Part

Position

Damages

Severity

Repair mode

Door

Back left

Dented

Diameter (mm) > 20

Smart Repair

6



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Scratched

Length (cm) > 10

Repair

7



Part

Position

Damages

Severity

Repair mode

Door

Front right

Hail damaged

Diameter (mm) > 20

Smart Repair

8



Part

Position

Damages

Severity

Repair mode

Wing

Front right

Dented

Diameter (mm) > 20

Repair

9



Part

Position

Damages

Severity

Repair mode

Alloy wheel 16"

Front right

Scratched

-

Lumpsum repair

10



Part

Position

Damages

Severity

Repair mode

Bumper

Front

Scratched

Length (cm) > 10

Repair

11



Part

Position

Damages

Severity

Repair mode

Bonnet

-

Dented

Diameter (mm) > 20

Smart Repair

Interior damage

4



●

●

●

Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

12



●

Part	Interior roof lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair