


Vehicle details

VIN	VNVK14009 65143094	Brand	NISSAN	Maintenance date	-
Licence Plate	J0-42-FL	Model	MICRA IG-T 100 N-Connecta 5d	Maintenance mileage	-
Registration date	03/08/2020	Year	2020	Exterior Color	White Solid
Odometer	149 700 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	14/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Bridgestone 185/55/16 Summer 4.0 mm		Bridgestone 185/55/16 Summer 4.0 mm	
Bridgestone 185/55/16 Summer 7.0 mm		Bridgestone 185/55/16 Summer 7.0 mm	

Exterior

1



Part

Bonnet

Position

-

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

2



Part

Bumper

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

3



Part

Door

Position

Back right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

4



Part

Bumper

Position

Back left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

5



Part

Wing

Position

Back left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

6



Part

Door

Position

Back left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

7



Part

Door

Position

Front left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

8



Part

Exterior door mirror shell

Position

Front left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

9



Part

Exterior door mirror shell

Position

Front right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●