


## Vehicle details

|                   |                    |              |                                            |                           |              |
|-------------------|--------------------|--------------|--------------------------------------------|---------------------------|--------------|
| VIN               | VNVK1400X 65693436 | Brand        | NISSAN                                     | Maintenance date          | -            |
| Licence Plate     | J7-83-JK           | Model        | MICRA IG-T 100 ActieAuto 5d N-Connecta APL | Maintenance mileage       | -            |
| Registration date | 25/08/2020         | Year         | 2020                                       | Exterior Color            | Red Metallic |
| Odometer          | 95 556 km          | Engine size  | 999                                        | interior Color            | Grey         |
| Fuel              | Petrol             | Body Type    | -                                          | Next technical inspection | -            |
| Seats             | -                  | Transmission | Manual                                     | CO2                       | -            |
| Doors             | 5                  | Gears        | 5                                          |                           |              |

## Inspection Details

|                 |            |                 |               |
|-----------------|------------|-----------------|---------------|
| Inspection date | 25/08/2025 | Inspection loc. | Ayvens Veghel |
|-----------------|------------|-----------------|---------------|



## Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Cruise control          | ✓ |
| GPS system              | ✓ |
| Alloy wheel rims        | ✓ |
| Metallic paint          | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |
| Led lighting            | ✓ |


## Removable element

|                   |   |
|-------------------|---|
| Spare wheel kit   | ✓ |
| Rear parcel shelf | ✓ |

## Technical Document

|                  |   |
|------------------|---|
| User manual      | ✓ |
| Warranty booklet | ✓ |
| Spare key        | ✓ |
| Remote key       | ✓ |

## Tyres

|                                     |                                                                                     |                                     |                                                                                       |
|-------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
| Michelin 195/55/16 Summer 3.0 mm    |  | Michelin 195/55/16 Summer 2.5 mm    |  |
| Bridgestone 195/55/16 Summer 4.0 mm |                                                                                     | Bridgestone 195/55/16 Summer 4.0 mm |                                                                                       |

## Exterior

1



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Front left         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

2



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Front right        |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

4



|             |                  |
|-------------|------------------|
| Part        | Bumper           |
| Position    | Front            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

5



|             |                  |
|-------------|------------------|
| Part        | Roof             |
| Position    | -                |
| Damages     | Chemical deposit |
| Severity    | -                |
| Repair mode | Lumpsum repair   |

## Interior damage

3



|             |             |
|-------------|-------------|
| Part        | Fabric seat |
| Position    | Front right |
| Damages     | Worn out    |
| Severity    | -           |
| Repair mode | For info    |