


## Vehicle details

|                   |                    |              |                                                    |                           |               |
|-------------------|--------------------|--------------|----------------------------------------------------|---------------------------|---------------|
| VIN               | VNVK1400X 65962535 | Brand        | NISSAN                                             | Maintenance date          | -             |
| Licence Plate     | J3-41-RZ           | Model        | MICRA IG-T 100 ActieAuto Xtronic 5d N-Connecta APL | Maintenance mileage       | -             |
| Registration date | 08/10/2020         | Year         | 2020                                               | Exterior Color            | Blue Metallic |
| Odometer          | 120 514 km         | Engine size  | 999                                                | interior Color            | Black         |
| Fuel              | Petrol             | Body Type    | -                                                  | Next technical inspection | -             |
| Seats             | -                  | Transmission | Automatic                                          | CO2                       | -             |
| Doors             | 5                  | Gears        | -                                                  |                           |               |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 13/10/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| GPS system                 | ✓ |
| Alloy wheel rims           | ✓ |
| Automatic Gearbox          | ✓ |
| Heating seats              | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |

## Removable element

|                   |   |
|-------------------|---|
| Rear parcel shelf | ✓ |
|-------------------|---|

## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Warranty booklet        | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| Continental 195/55/16 Summer 4.0 mm | Continental 195/55/16 Summer 6.0 mm |
| Bridgestone 195/55/16 Summer 5.0 mm | Bridgestone 195/55/16 Summer 7.0 mm |

## Exterior

1



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Front left         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

3



|             |            |
|-------------|------------|
| Part        | Step plate |
| Position    | Back left  |
| Damages     | Scratched  |
| Severity    | -          |
| Repair mode | For info   |

4



|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Front right        |
| Damages     | Dent & Chips       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

5



|             |                 |
|-------------|-----------------|
| Part        | Alloy wheel 16" |
| Position    | Front right     |
| Damages     | Scratched       |
| Severity    | -               |
| Repair mode | Lumpsum repair  |

6



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Back right         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

## Interior damage

2



|             |                   |
|-------------|-------------------|
| Part        | Interior cleaning |
| Position    | Front             |
| Damages     | Stained/dirty     |
| Severity    | -                 |
| Repair mode | Cleaning          |