


Vehicle details

VIN	VR1J45GFU LY026667	Brand	DS	Maintenance date	-
Licence Plate	J8-40-BP	Model	DS 7 Crossback PureTech 180 Business auto 5d	Maintenance mileage	-
Registration date	06/07/2020	Year	2020	Exterior Color	Brown Metallic
Odometer	119 795 km	Engine size	1598	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	11/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Xenon projectors	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Pirelli 215/65/17 Winter 4.4 mm	Pirelli 215/65/17 Winter 3.9 mm	
Bridgestone 215/65/17 Winter 3.6 mm	Bridgestone 215/65/17 Winter 3.4 mm	

Exterior

1



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●●

2



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●

3



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●

4



Part	Wing
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●

5



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●●

6



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

Interior damage

7



Part	Radio with Sat Nav
Position	Front
Damages	Not conform
Severity	-
Repair mode	Replace