

INSPECTION REPORT

End of contract

GENERAL INFO

File	293293
License plate	1XQK052
Vehicle identification number	VR1JRHNSJLY015560
Dossier	2019269221
Make	DS DS7 1.2 130 Be Chic
Mileage	104424
First registration	01/08/2020
client availability date	11/09/2025
inspectionDate	17/09/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES


Damages	Type	Acceptable
135	Bumper Rear // Replace & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
266	Foglight Rear // Replacement	N
13	Bumper Front // Painting	N
237	Wing Front right / Trim / Replace	N
32	Front Bonnet // Painting	Y
72	Side View Mirror Left // Painting	Y
83	Door Front Left // Painting	N
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
421	Seat Front Right // Repair	Y
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
840	Interior Cleaning // Large	N

Damage Pictures






Damage within Renta-norm-



Roof // Polish-scratch



Seat Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch




Wheel Two Tone Front Right // Repair-scratch




Dashboard / Steering Wheel / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Front Bonnet // Painting-scratch




Side View Mirror Left // Painting-scratch



Door Front Left // Painting-scratch



Door Front Right // Repair & Painting-dent



Wing Rear Right // Repair & Painting-scratch + dent



Interior // Repair 1-Incinerated



Interior Cleaning // Large-dirty



Bumper Rear // Replace & Painting-cracked




Foglight Rear // Replacement-cracked



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front // Painting-scratch