

Damage Review



Jobnr	141359
Fleet	BCA
Lease	
Driver	Bestuurder
Location	
Date	09-10-2025
Date Hour	13:23

Make	PEUGEOT
Model	RIFTER
Type	
Licenseplate	2GEH837
Chassisnr	VR3ECYHWCJJ857505
Color	Wit
First Registration	
Mileage	280592
VP/VU	VP
Fuel	diesel
Fuel Level	3/8
Total Keys	1
Seats MVP	5

Check			
COC	No	Safety Kit	No
Registration doc	No	Triangle	No
Insurance doc	No	GPS	No
Manual	No	Fuel Card	No
Service book	No	Alarm	No
Fire extinguisher	Yes	Service Needed	No
Rear Shelf	Yes		

Remarks

27 schadelijnen

Financial Result Damage Appraisal		
	Acceptable Total	0,00 €
	Not Acceptable Total	0,00 €
	Depreciation	0 %
	Not Acceptable Depreciated Total	0,00 €
	Total Damages	0,00 €
	Total Damages (Depreciation incl.)	0,00 €
		(bedragen excl. BTW)


Signatures

Damage advisor

Client
BCA



exterior	1 BumperF	BUMPERPART NOT PAINTED	NA	scratch	Replace	€ 0
interior	2 Dashboard	RADIO	NA	N comf / out of order	Repair	€ 0
interior	2 Dashboard	MOULDING	NA	missing	Replace	€ 0
exterior	20 SillR	SILLR	NA	scratch + dent	SR - Spot repair	€ 0
interior	21 CoverR	COVER RIGHT	NA	scratch	Replace	€ 0
interior	16 Rearshelf	REARSHELF	NA	tear	Replace	€ 0
interior	20 CoverL	COVER LEFT	NA	scratch	Replace	€ 0
interior	29 Cleaning	CLEANING	NA	dirty	Cleaning	€ 0
interior	22 DoorpanelFL	DOORPANEL FL	NA	scratch	SR - Structure	€ 0
exterior	16 Roof	AERIAL	NA	missing	Replace	€ 0
interior	30 Missing	INSCRIPTION DOCUMENT	NA	missing	Replace	€ 0
interior	30 Missing	COC DOCUMENT	NA	missing	Replace	€ 0
interior	30 Missing	2ND KEY	NA	missing	Replace	€ 0
exterior	13 BumperR	BUMPER REAR	NA	tear	Replace	€ 0
exterior	30 Extra	LCV REMOVE STICKERS S	NA	Remainder stickers	Remove stickers	€ 0
exterior	27 WheelRR	WHEELCOVER RR	NA	missing	Replace	€ 0
exterior	28 WheelFR	WHEELCOVER FR	NA	missing	Replace	€ 0
exterior	18 WingRR	WING RR	NA	dent	SR - PDR	€ 0
exterior	23 WingFR	WING FR	NA	dent	SR - PDR	€ 0
exterior	30 Extra	COMMERCIAL PICTURES	A			€ 0
interior	2 Dashboard	DASHBOARD	A	scratch	SR - Structure	€ 0
interior	23 DoorpanelFR	DOORPANEL FR	A	scratch	SR - Structure	€ 0
interior	19 CoverBonnet	COVER BONNET	A	scratch	SR - Structure	€ 0
exterior	8 DoorFL	DOOR FL	A	scratch	SR - Touch up	€ 0
exterior	10 DoorRL	DOOR RL	A	scratch	SR - Touch up	€ 0
exterior	8 DoorFL	MOULDING FL	A	scratch	Replace	€ 0
exterior	15 BonnetR	BONNET	A	scratch	SR - Polish	€ 0

General Pictures





Damage Appraisal



exterior	1 BumperF	BUMPERPART NOT PAINTED	NA scratch	Replace	€ 0
----------	-----------	------------------------	------------	---------	-----



interior	2 Dashboard	RADIO	NAN comf / out of order	Repair	€ 0
----------	-------------	-------	-------------------------	--------	-----



interior	2 Dashboard	MOULDING	NA missing	Replace	€ 0
----------	-------------	----------	------------	---------	-----



exterior	20 SillR	SILLR	NA scratch + dent	SR - Spot repair	€ 0
----------	----------	-------	-------------------	------------------	-----



interior	21 CoverR	COVER RIGHT	NA scratch	Replace	€ 0
----------	-----------	-------------	------------	---------	-----



interior	16 Rearshelf	REARSHELF	NA tear	Replace	€ 0
----------	--------------	-----------	---------	---------	-----



interior	20 CoverL	COVER LEFT	NA scratch	Replace	€ 0
----------	-----------	------------	------------	---------	-----



interior	29 Cleaning	CLEANING	NA dirty	Cleaning	€ 0
----------	-------------	----------	----------	----------	-----



interior	22 DoorpanelFL	DOORPANEL FL	NA scratch	SR - Structure	€ 0
----------	----------------	--------------	------------	----------------	-----



exterior	16 Roof	AERIAL	NA missing	Replace	€ 0
----------	---------	--------	------------	---------	-----



interior	30 Missing	INSCRIPTION DOCUMENT	NA missing	Replace	€ 0
interior	30 Missing	COC DOCUMENT	NA missing	Replace	€ 0
interior	30 Missing	2ND KEY	NA missing	Replace	€ 0



exterior	13 BumperR	BUMPER REAR	NA tear	Replace	€ 0
----------	------------	-------------	---------	---------	-----



exterior	30 Extra	LCV REMOVE STICKERS S	NA Remainder stickers	Remove stickers	€ 0
----------	----------	-----------------------	-----------------------	-----------------	-----



exterior	27 WheelRR	WHEELCOVER RR	NA missing	Replace	€ 0
----------	------------	---------------	------------	---------	-----



exterior	28 WheelFR	WHEELCOVER FR	NA missing	Replace	€ 0
----------	------------	---------------	------------	---------	-----




exterior	18 WingRR	WING RR	NA dent	SR - PDR	€ 0
----------	-----------	---------	---------	----------	-----


Kras oppervlakkig



exterior	23 WingFR	WING FR	NA dent	SR - PDR	€ 0
----------	-----------	---------	---------	----------	-----



exterior	30 Extra	COMMERCIAL PICTURES	A	€ 0
----------	----------	---------------------	---	-----



interior	2 Dashboard	DASHBOARD	A scratch	SR - Structure	€ 0
----------	-------------	-----------	-----------	----------------	-----



interior	23 DoorpanelFR	DOORPANEL FR	A scratch	SR - Structure	€ 0
----------	----------------	--------------	-----------	----------------	-----



interior	19 CoverBonnet	COVER BONNET	A scratch	SR - Structure	€ 0
----------	----------------	--------------	-----------	----------------	-----



exterior	8 DoorFL	DOOR FL	A scratch	SR - Touch up	€ 0
----------	----------	---------	-----------	---------------	-----



exterior	10 DoorRL	DOOR RL	A scratch	SR - Touch up	€ 0
----------	-----------	---------	-----------	---------------	-----



exterior	8 DoorFL	MOULDING FL	A scratch	Replace	€ 0
----------	----------	-------------	-----------	---------	-----



exterior	15 BonnetR	BONNET	A scratch	SR - Polish	€ 0
----------	------------	--------	-----------	-------------	-----

Oppervlakkig



Vehicle Condition	Interior: dirty
	Exterior: dirty

Tyres			
Type	Summer	Flat/RSC	No
Spare Tyre	Yes	Repair Kit	No
Front Left			
Profile	5	Side Damage	No
Front Right			
Profile	5	Side Damage	No
Rear Left			
Profile	5	Side Damage	No
Rear Right			
Profile	5	Side Damage	No