



Peugeot Partner (Segm. B1): 1WSM395

Vinnumber:	VR3EFBHYBKJ698337	Versionname:	Partner L2 Heavy Premium 1.6 BlueHDi S&S
First Registrationdate:	29/08/2019	Fiscalpower:	100pk/cv
Expertise Mileage:	203972	Power Kw:	73
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	Tow bar fixed
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		


Tyres

205/60/16/96 W				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/60 R 16 96 W
Tyre size FR				205/60 R 16 96 W
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Non-conforme, Replace



Service, Maintenance, Check



GPS, Not functioning (well), Check



Interior, Not original part, Check



Floor covering FL, Missing, Check



Floor covering FL, Worn, Acceptable



Seat cover FL, Worn, Acceptable




Steering wheel, Worn, Acceptable



Door panel FL, Scratch(es), Acceptable



Backrest cover FL, Stain, Acceptable



Armrest, Worn, Acceptable



Seat cover FR, Stain, Acceptable



Seat cover FR, Stain, Acceptable



Floor covering FR, Missing, Check



Door panel RR, Scratch(es), Acceptable



Seat cover FL, Stain, Acceptable



Dashboard, Glue residues, Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Smart repair



Roof pillar L, Dent(s), Repair and paint (complete)



Steel rim FL, Rust, Acceptable



Door FL, Dent(s) and scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door trim FL, Scratch(es), Acceptable




Wing RL, Dent(s) and scratch(es), Acceptable



Steel rim RL, Rust, Acceptable



Wing RL, Repaired, Check



Rear bulkhead lining, Damaged, Acceptable





Internal boot lining R, Broken, Replace



Partition wall, Scratch(es), Acceptable



Boot door panel RR, Dent(s) and scratch(es), Acceptable



Boot door panel RL, Dent(s) and scratch(es), Acceptable



Bumper R, Deformed / Strained, Replace




Boot door panel RL, Dent(s) and scratch(es), Acceptable



Boot door panel RR, Dent(s), Acceptable





Door window FR, Missing, Replace



Outside rear-view mirror housing R, Broken, Replace



Step R, Dent(s) and scratch(es), Acceptable




Step R, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Steel rim RR, Rust, Acceptable



Door RR, Scratch(es), Acceptable



Door trim FR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Wheel cover FR, Missing, Replace



Steel rim FR, Rust, Acceptable



Door FR, Dent(s) and scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Roof, Dent(s), Paintless dent repair



Bodywork, Not original part, Check

