



Peugeot Partner: VDH08S

Vinnumber:	VR3EFYHWCKN547555	Versionname:	Partner 1.5 BlueHDi 55kW Standaard Premium
First Registrationdate:	21/11/2019	Fiscalpower:	650kg
Expertise Mileage:	154284	Power Kw:	55
Bodytype:		Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Diesel	Parking lot:	911
Number of seats:	2		
Type of rims (mounted):	Steel		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	1	Central consol F
GPS		Hook
Manual climate control		Sliding door right-side
Windows electric F		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 95 / H / Steel	5,6 mm	Continental	All season
	Right	195 / 65 / 15 / 95 / H / Steel	5,4 mm	Continental	All season
Rear	Left	195 / 65 / 15 / 91 / H / Steel	4,2 mm	Vredestein	All season
	Right	195 / 65 / 15 / 91 / H / Steel	3,2 mm	Vredestein	All season

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Malfunction, Not functioning (well), Diagnosis



Wing FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



[Damage Picture - 2](#)



Bumper F, Scratch(es), Smart repair



Bumper FM, Scratch(es), Repair and paint (complete)



Headlight L, Scratch(es), Replace



Wing FR, Dent(s), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Outer sill R, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Rust, Repair and paint (complete)



Roof, Rust, Repair and paint (complete)

