



PEUGEOT 508 SW: 2CBT050			
Vinnumber:	VR3F45GBTNY519500	Versionname:	508 SW 1.6 Hybrid 360 e-EAT8 PSE (PHEV)
First Registrationdate:	24/05/2022	Fiscalpower:	265kW/360pk 5D/P Auto-8
Expertise Mileage:	59988	Power Kw:	147
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	4 Wheel-drive	Parking lot	c323
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Clean		
Options			
Number of keys total	2	Radio	
Number keys remote	2	Sun Roof electric	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Navigation with screen			
Airco electronic			
Rims alloy			
Limited Technical Inspection			
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK
Tyres			
Summer tyres:	245/35/20/95 Y		
	Fr.L.	Continental: 5 mm	Fr.R.
	Re.L.	Michelin: 2 mm	Re.R.
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			2.0
Tyre profile depth RR			2.0
Tyre size FL			245/35 ZR 20 95 Y
Tyre size FR			245/35 ZR 20 95 Y
Tyre size RL			245/35 ZR 20 95 Y
Tyre size RR			245/35 ZR 20 95 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Bumper F, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Tyre FL, Deformed / Strained, Replace



Alloy rim FL polished, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing FL, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Spot repair





Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Tyre RR, Worn, Acceptable



Wing RR, Dent(s), Paintless dent repair



Roof pillar R, Dent(s), Paintless dent repair



Roof, Deformed / Strained, Repair and paint (complete)

