



Peugeot 508: K772KD

Vinnnumber:	VR3F45GFTKY190187	Versionname:	508 1.2 PureTech 96kW S&S Blue Lease GT Line SW EAT8 (NEDC)
First Registrationdate:	6/01/2021	Fiscalpower:	
Expertise Mileage:	183009	Power Kw:	96
Bodytype:		Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	1019
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Lining semi-leather
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors
		Hook

Degree of wear

215/55/17/94 W				
Summer tyres:	Fr.L.	Michelin: 3,7 mm	Fr.R.	Michelin: 3,3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 4,3 mm
Tyre profile depth FL				3.7
Tyre profile depth FR				3.3
Tyre profile depth RL				5.0
Tyre profile depth RR				4.3
Tyre size FL				215/55 R 17 94 W
Tyre size FR				215/55 R 17 94 W
Tyre size RL				215/55 R 17 94 W
Tyre size RR				215/55 R 17 94 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Dashboard, Scratch(es), Smart repair



Wing FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint

