



Peugeot 508 (KKL): 1YNP708

Vinnumber:	VR3F45GFTLY031807	Versionname:	508 SW Allure 1.6 PureTech 180pk/cv S&S 5p EAT8
First Registrationdate:	13/10/2020	Fiscalpower:	
Expertise Mileage:	155709	Power Kw:	133
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		
Maintenance	geen melding db		

Options

Type of Maintenance book	Digital maintenance	Luggage cover	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
GPS			
Number of keys total	2		

Tyres

Tyre size RL	215/55 R 17 94 V
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	2.0
Tyre profile depth RR	7.0
Tyre size FR	215/55 R 17 94 V
Tyre make FR	256

215/55/17/94 V

Summer tyres:	Fr.L.	Continental: 2,1 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 7,3 mm	Re.R.	Continental: 7 mm

Tyre size RR	215/55 R 17 94 V
Tyre make RR	256
Tyre profile depth FL	2.1
Tyre size FL	215/55 R 17 94 V
Tyre make FL	256
Tyre profile depth RL	7.3
Tyre type FR	Summer
Tyre type RR	Summer
Tyre make RL	256

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Seat cover FR, Stain, Cleaning



Seat cover FL, Worn, Check



Backrest cover FL, Worn, Check



Seat cover FL, Stain, Acceptable




Backrest cover FL, Stain, Acceptable



Bumper F, Scratch(es), Spot repair



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Door FL, Dent(s), Paintless dent repair



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Wheel aperture RR, Dent(s), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)




Outer door handle FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Paintless dent repair

