



Peugeot 508: J661DD

Vinnnummer:	VR3FBYHZRKY073524	Versionname:	508 1.5 (outgoing) BHD1 96kW S&S BI Active Avantage EAT8
First Registrationdate:	27/08/2020	Fiscalpower:	
Expertise Mileage:	207967	Power Kw:	96
Bodytype:		Body colour:	Gris Amazonite
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Diesel	Parking lot:	681
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors
		Tow bar removable

Degree of wear

215/55/17/98 W				
Winter tyres:	Fr.L.	Michelin: 2,8 mm	Fr.R.	Michelin: 2,5 mm
	Re.L.	Michelin: 5,5 mm	Re.R.	Michelin: 5,4 mm
Tyre profile depth FL				2.8
Tyre profile depth FR				2.5
Tyre profile depth RL				5.5
Tyre profile depth RR				5.4
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 W
Tyre size RR				215/55 R 17 98 W
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Interior, Dirty, Cleaning



Door panel RL, Tear, Smart repair



Interior, Stain, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Crack, Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Roof, Hail damage, Paintless dent repair (hail)

