



PEUGEOT 508: 2AKP628

Vinnnumber:	VR3FBYHZTMY008563	Versionname:	
First Registrationdate:	27/04/2021	Fiscalpower:	
Expertise Mileage:	87314	Power Kw:	
Bodytype:		Body colour	Dark Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3209
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	+14100 km		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

225/40/19/96 V				
Winter tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/40 R 19 96 V
Tyre size FR				225/40 R 19 96 V
Tyre size RL				225/40 R 19 96 V
Tyre size RR				225/40 R 19 96 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				264
Tyre make FR				264
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1269,47
Bumper F, Scratch(es), Spot repair	144,58



Bumper F, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Door FL, Dent(s) and scratch(es), Acceptable

0,00



Door RL, Dent(s), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Tailgate / Boot, Scratch(es), Acceptable

0,00





Wing FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door FR, Dent(s), Paintless dent repair	248,16
---	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Door RR, Dent(s), Acceptable	0,00
------------------------------	------



Wing RR, Dent(s), Repair and paint (complete)	478,65
---	--------



Alloy rim RR polished, Scratch(es), Acceptable	0,00
--	------

