



Peugeot 508: L982ZR

Vinnumber:	VR3FBYHZTMY523174	Versionname:	508 1.5 BlueHdi 96kW S&S Blue Lease Active EAT8
First Registrationdate:	6/09/2021	Fiscalpower:	
Expertise Mileage:	138003	Power Kw:	96
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Diesel	Parking lot	185
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 16 / 99 / H / Aluminium	5,0 mm	Michelin	Winter
	Right	215 / 60 / 16 / 99 / H / Aluminium	5,0 mm	Michelin	Winter
Rear	Left	215 / 60 / 16 / 99 / H / Aluminium	4,8 mm	Michelin	Winter
	Right	215 / 60 / 16 / 99 / H / Aluminium	4,7 mm	Michelin	Winter

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0


Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Stone chip(s), Repair and paint (complete)



Roof pillar L, Dent(s), Paintless dent repair




Bonnet, Chemical polution, Polish



Windscreen, Scratch(es), Replace



Wing FR, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Roof, Dent(s) and scratch(es), Repair and paint (complete)

