



Peugeot 508 (KKL): 1YSS658

Vinnnumber:	VR3FCYHZJLY039237	Versionname:	508 SW Allure 1.5 BlueHDi 130pk/cv S&S 5p
First Registrationdate:	1/12/2020	Fiscalpower:	
Expertise Mileage:	27498	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+ 28800 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

215/55/17/98 V				
Winter tyres:	Fr.L.	Fulda: 10 mm	Fr.R.	Fulda: 10 mm
	Re.L.	Fulda: 10 mm	Re.R.	Fulda: 9 mm
Tyre profile depth FL				10.0
Tyre profile depth FR				10.0
Tyre profile depth RL				10.0
Tyre profile depth RR				9.0
Tyre size FL				215/55 R 17 98 V
Tyre size FR				215/55 R 17 98 V
Tyre size RL				215/55 R 17 98 V
Tyre size RR				215/55 R 17 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				2484
Tyre make RR				2484

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Missing, Replace



Engine insulation, Hole, Replace



Bonnet, Dent(s), Acceptable



Bumper F, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Luggage compartment cover, Missing, Replace



Bumper R, Scratch(es), Spot repair



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Paintless dent repair

