


PEUGEOT 508 SW: 1YSQ398

Vinnnumber:	VR3FCYHZJLY046866	Versionname:	1.5 BlueHdi 130 S&S BVM6 Active
First Registrationdate:	30/11/2020	Fiscalpower:	
Expertise Mileage:	189801	Power Kw:	96
Bodytype:		Parking lot	3323
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Grey
Fueltype:	Diesel		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Cruise Control			
Type of climate control	Autom climate control		
Number of keys total	2		
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		

Limited Technical Inspection
Tyres

Tyre size RL	235/55 R 18 100 V
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	3.0
Tyre profile depth RR	3.0
Tyre make FR	2480
Tyre size FR	235/55 R 18 100 V
Tyre make RR	2480
Tyre size RR	215/60 R 16 99 H

235/55/18/100 V				
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

Tyre profile depth FL	3.0
Tyre make FL	2480
Tyre size FL	235/55 R 18 100 V
Tyre type FR	Winter
Tyre profile depth RL	3.0
Tyre type RR	Winter
Tyre make RL	2480

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Total cost ex VAT	895,65
--------------------------	---------------

Interior, Worn, Acceptable	0,00
-----------------------------------	-------------



Alloy rim FL, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Repair and paint (complete) 289,07



Reflector, Broken, Replace 27,50



Wing FR, Scratch(es), Acceptable 0,00



Door FR, Dent(s) and scratch(es), Repair and paint (complete) 434,50



Outer door handle FR, Scratch(es), Acceptable 0,00



Step R, Dent(s) and scratch(es), Spot repair 144,58



Door RR, Dent(s) and scratch(es), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00



Rear window, Scratch(es), Replace 0,00

