

PEUGEOT 308
308 SW BlueHDi 130ch S&S BVM6 Active
Pack

VIN NO VR3FCYHZLNY568980
Registration Number GH329DN



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251014084748
Inspection Date / Place	2025-10-14 / BCA ANGOULEME	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1499
Engine Size	1.5	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warranty			

Equipment


Central locking	Electrically folding wing mirrors	Rear parking sensors	Stability control
Power assisted steering	Electrically adjustable seats	Radio	Alloys wheels
Cruise control	Satellite navigation		

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage


5 Dommages



5 Dommages



	Component	Damage	Comments
1	Fender / Back Left	Paint / Scratch / Scuff	
2	Floor Carpet	Interior / Worn - out	
3	Door / Back Left	Paint / Scratch / Scuff	
4	Floor Carpet	Interior / Dirty	
5	Floor Carpet	Interior / Dirty	
6	Mirror / Front Right	Paint / Scratch / Scuff	
7	Door / Front Left	Bodywork / Dent / Dent	
8	Bumper / Front	Bodywork / Breakage	
9	Floor Carpet	Interior / Not Working	
10	Floor Carpet	Interior / Dirty	



1. Fender / Back Left
Paint / Scratch / Scuff -



2. Floor Carpet
Interior / Worn - out -



3. Door / Back Left
Paint / Scratch / Scuff -



4. Floor Carpet
Interior / Dirty -



5. Floor Carpet
Interior / Dirty -



6. Mirror / Front Right
Paint / Scratch / Scuff -



7. Door / Front Left
Bodywork / Dent / Dent -



8. Bumper / Front
Bodywork / Breakage -



9. Floor Carpet
Interior / Not Working -



10. Floor Carpet
Interior / Dirty -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.