



Peugeot 508 (KKL): 1YWG796

Vinnnumber:	VR3FCYHZTLY053802	Versionname:	508 SW Allure 1.5 BlueHDi 130pk/cv S&S 5p EAT8
First Registrationdate:	11/01/2021	Fiscalpower:	
Expertise Mileage:	99260	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	plus 16800 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

215/55/17/98 W				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				2.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 W
Tyre size RR				215/55 R 17 98 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper F, Scratch(es), Repair and paint (complete)





Bonnet, Chemical polution, Polish




Wing FL, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Polish

