

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	288765
License plate	2CDY714
Vehicle identification number	VR3FPHNPLNY554493
Dossier	2020 353 151
Make	Peugeot 308 1.2 110 Active Pac
Mileage	53191
First registration	20/06/2022
client availability date	14/07/2025
inspectionDate	15/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
91	Rocker Panel Left // Smart Repair Medium	Y
114	Wing Rear Left // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
316	Tyre Front Left // Replace	Y
344	Wheel Front Right / Wheel Cover / Replace	Y
346	Tyre Front Right // Replace	Y


Damage Pictures




Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wheel Front Right / Wheel Cover / Replace-missing



Tyre Front Right // Replace-worn



Tyre Front Left // Replace-worn