

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	287355
License plate	2CRB350
Vehicle identification number	VR3FRHNPLNY617320
Dossier	2021 363 314
Make	Peugeot 308 SW 1.2 110 Active
Mileage	57915.00
First registration	25/10/2022
	03/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	Y
134	Bumper Rear // Repair & Painting	N
137	Bumper Rear // Replace without painting	N
184	Wing Rear Right // Repair & Painting	N
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	Y
344	Wheel Front Right / Wheel Cover / Replace	N
540	Interior // Repair 1	N
860	Interior Cleaning // Small	N

Damage Pictures



Wheel Front Right / Wheel Cover / Replace-scratch



Bumper Rear // Replace without painting-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch




Wheel Front Left / Wheel Cover / Replace-scratch




Bumper Rear // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Windshield // Replace-cracked



Interior // Repair 1-Incinerated

