



Peugeot 208: H184HB

Vinnumber:	VR3UBYHYJLT004519	Versionname:	208 1.5 BlueHDi 75kW Blue Lease Active
First Registrationdate:	30/01/2020	Fiscalpower:	
Expertise Mileage:	197847	Power Kw:	75
Bodytype:		Body colour	Blanc Banquise standaardlak
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Diesel	Parking lot	539
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Luggage cover
GPS		Rear parking sensors
Manual climate control		
Windows electric F		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Steel	4,3 mm	Goodyear	Summer
	Right	195 / 55 / 16 / 87 / H / Steel	4,2 mm	Goodyear	Summer
Rear	Left	195 / 55 / 16 / 87 / H / Steel	3,8 mm	Goodyear	Summer
	Right	195 / 55 / 16 / 87 / H / Steel	4,0 mm	Goodyear	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Dirty, Cleaning



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)





Wing RL, Scratch(es), Repair and paint (complete)



Bonnet, Hail damage, Paintless dent repair (hail)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Hail damage, Paintless dent repair (hail)



Bodywork, Chemical polution, Polish



Door RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)

